

Technical finding

Terminal L2 insulation

TechSnap Demo Service

DATE

Oct 21, 2026

CUSTOMER

Example Manufacturing

LOCATION

Production hall A

EQUIPMENT

Distribution cabinet RH-01

SEVERITY

High

STATUS

Open

01 Finding

Visible insulation damage near terminal L2. Cause not yet established.


RECOMMENDED ACTION

Qualified inspection of the connection and conductor; measurements according to the findings.

MEASURED VALUES

No measurements taken.

Photographs · 1



Terminal L2 / photo 1

TECHNICIAN

Demo technician

Technical record. This document does not replace a statutory inspection report.